


Progress and status

OPERATIONS	FORENSICS	PERSONNEL	HEALTH, SAFETY AND WELLBEING	CHALLENGES	CONTINUOUS IMPROVEMENTS
<ul style="list-style-type: none"> Reconnaissance barrier at 2153m Refuge chamber at 2008m 	<ul style="list-style-type: none"> Continuing as per New Zealand Police Plan 	<ul style="list-style-type: none"> Consulting on staffing requirements for 2021 Agency staff to observe 1 minute silence at 3.44pm to mark 10th anniversary on 19/11/20 	<ul style="list-style-type: none"> Continuing with weekly products of combustion sampling 	<ul style="list-style-type: none"> Risk assessment/ planning for Families 10th anniversary site event 40% megabolts completed Explosion debris 	<ul style="list-style-type: none"> No changes to report

▲ Tracking ahead of time
 ● Tracking on time
 ■ Delayed

Drift recovery progress



Sequence of events timeline

