

Progress and status

OPERATIONS



- Recovery to roof fall at 2260m
- Removed loader driven by Daniel Rockhouse at time of explosion
- Removed substation from B1 roadway

FORENSICS



- Completed forensics in B1 roadway with LIDAR scanning
- Focusing on forensics in B3 roadways

PERSONNEL



- Recruiting for two new mining staff

HEALTH, SAFETY AND WELLBEING



- On target for all aspects that are monitored and reported

CHALLENGES




- Budget pressures
- Removing explosion-affected debris from PBiS

CONTINUOUS IMPROVEMENTS



Roof fall recovery progress



Sequence of events timeline

